

Jervis Webb FOIA Review
CD Index
March 1, 2012

Doc #	Document Description	Total Pages	Folder	Pages Marked for Redaction
3	DTSC EPA ID Profile for ID #CAD008339467, Webb, Jervis B. Co of California, http://hwts.dtsc.ca.gov/report_search.cfm?id=5 , June 17, 2011.	4	No Redactions	None
6	Manta.com Profile for Reliable Steel Building Prods, www.manta.com , June 20, 2011.	3	No Redactions	None
8	DTSC EPA ID Profile for ID #CAL000288679, Reliable Steel Bldg. Products Inc., http://hwts.dtsc.ca.gov/report_search.cfm?id=5 , June 17, 2011.	1	No Redactions	None
13	DTSC EPA ID Profile for ID #CAL000289605, United Motor Club Inc., http://hwts.dtsc.ca.gov/report_search.cfm?id=5 , June 17, 2011.	1	No Redactions	None
19	Jervis B. Webb Co. company website, About Webb, www.jervisbwebb.com/AboutUs_Details.aspx , June 20, 2011.	3	No Redactions	None
20	Fundinguniverse.com profile, Jervis B. Webb Company profile, www.fundinguniverse.com/company-histories/Jervis-B-Webb-Company-Company-History.html , June 20, 2011.	5	No Redactions	None
22	EPA Envirofacts, Facility Detail Report for Webb Firestone Blvd. Property, www.epa.gov/enviro/facts/multisystem.html , June 17, 2011.	4	No Redactions	None
28	DTSC EPA ID Profile for ID #CAD063798995, Jervis B Webb Co of California http://hwts.dtsc.ca.gov/report_search.cfm?id=5 , June 17, 2011.	4	No Redactions	None
31	WhitePages listing for Reliable Steel Building Prods, 9301 Rayo Ave., South Gate, CA	2	No Redactions	None
32	Yellow Pages listing for Reliable Steel Building Prods, 9301 Rayo Ave., South Gate, CA	1	No Redactions	None
34	"Jervis B. Webb Company Announces Completion of Acquisition to Daifuku Co., Ltd." press release	2	No Redactions	None
35	Daifuku Annual Report 2010 (Year ended March 31, 2010)	12	No Redactions	None
43	Preliminary Assessment/Site Inspection (prepared by Bechtel Environmental, Inc.; prepared for EPA Region IX), September 1, 1994.	49	No Redactions	None
44	Soil Closure Report (prepared by IT Corporation; prepared for Los Angeles Regional Water Quality Control Board), October 3, 2001.	208	No Redactions	None
45	Manta.com profile of United Motor Club Inc. at 5030 Firestone Blvd., South Gate, CA	2	No Redactions	None
47	Letter re: Hazardous Materials Underground Storage Closure Certification, 9301 Rayo Avenue, South Gate, Closure Application Number 175812, from County of Los Angeles Department of Public Works, to Jervis B. Webb Company, December 17, 1996.	1	No Redactions	None
48	Air Pollution Control District Permit to Operate for Jervis B. Webb Company of California, Permit Number 27853, September 23, 1968.	1	No Redactions	None
49	South Coast Air Quality Management District Permit to Operate for Jervis B. Webb Company, Permit Number 58084, August 6, 1987.	2	No Redactions	None
50	South Coast AQMD Facility Information Detail for Jervis B. Webb Co. of Cal., June 17, 2011.	6	No Redactions	None
51	State of California, Environmental Protection Agency, Department of Toxic Substances Control Imminent and Substantial Endangerment Determination and Remedial Action Order - Docket No. I&SE 09/10 - 010, February 2, 2010.	36	No Redactions	None
54	Additional Groundwater Investigation and Quarterly Monitoring Report for October to December 1998 (prepared by Erler & Kalinowski, Inc.; prepared for Jervis B. Webb Company), January 13, 1999.	132	No Redactions	None
55	Phase II Groundwater Investigation Report, Jervis B. Webb Company Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.), June 30, 1998.	86	No Redactions	None
56	Phase II Soil Investigation Report, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for Jervis B. Webb Company), February 18, 1998.	208	No Redactions	None

Jervis Webb FOIA Review
CD Index
March 1, 2012

Doc #	Document Description	Total Pages	Folder	Pages Marked for Redaction
57	Material Safety Data Sheet for Safety-Kleen 105 Solvent Recycled (prepared by Safety-Kleen), 2008.	13	No Redactions	None
58	Material Safety Data Sheet for Safety-Kleen 105 Solvent Virgin (prepared by Safety-Kleen), 2009.	11	No Redactions	None
59	Letter re: Report of Closure of Two Tanks at the Jervis B. Webb Company Facility, 9301 Rayo Avenue, South Gate, California (LACDPW File No. 017580-024024, Permit No. 175812) (EKI 961025.01), from Erler & Kalinowski, Inc., to Los Angeles County Department of Public Works, December 10, 1996.	78	No Redactions	None
60	Los Angeles Regional Water Quality Control Board Case Review Form for Jervis B. Webb, January 7, 2002.	4	No Redactions	None
62	Letter re: No Further Action for Soil Assessment and Cleanup for Industrial Waste Clarifier, Sumps T1 and T2 and Anodizing Area at Jervis B. Webb Company - 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate (SLIC No. 744), January 23, 2002.	2	No Redactions	None
63	Letter re: Soil Removal Activities, Jervis B. Webb of California, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, CA, SLIC No. 744, from IT Corporation, to California Regional Water Quality Control Board, Los Angeles Region, December 17, 2001.	23	No Redactions	None
64	Quarterly Progress Report for April to June 1999, Jervis B. Webb Company Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for Jervis B. Webb Company), July 30, 1999.	33	No Redactions	None
65	Quarterly Progress Report for July to September 1999, Jervis B. Webb Company Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for Jervis B. Webb Company), October 13, 1999.	58	No Redactions	None
66	Uniform Hazardous Waste Manifests for EPA ID Number CAD008339467, May 31, 1986 to March 12, 1996.	30	No Redactions	None
67	Letter re: Annual Groundwater Sampling Report - June 2005, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California, from Brown and Caldwell, to Regional Water Quality Control Board, July 28, 2005.	28	No Redactions	None
68	Letter re: Transmittal of Results for Additional Groundwater Investigation and Proposed Well Installation at the Jervis B. Webb Company Property at 5030 Firestone Boulevard, South Gate, California, from Erler & Kalinowski, Inc. to the California Regional Water Quality Control Board, October 21, 1998.	4	No Redactions	None
69	Letter re: Request for Reassessment of the Jervis B. Webb Company of California Property at 9301 Rayo Avenue, South Gate, California, Site EPA ID Number: CAD 008339467, from Erler & Kalinowski, Inc., to USEPA Region IX, January 16, 1997.	152	No Redactions	None
70	Letter re: Request for Reassessment of the Jervis B. Webb Company of California Property at 9301 Rayo Avenue, South Gate, California, EPA ID Number: CAD 008339467, from USEPA Region IX, to Jervis B. Webb Company, February 27, 1997.	2	No Redactions	None
71	Letter re: I&SE Order - Docket No. I&SE 09/10-010; Jervis B. Webb Company of California Site, from Morrison & Foerster to Department of Toxic Substances Control, March 8, 2010.	1	No Redactions	None
77	Letter re: Annual Groundwater Sampling Report - July 2004, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California, from Brown and Caldwell to RWQCB, July 22, 2004.	36	No Redactions	None
78	2011 News Release, "U.S. EPA Proposes to Add LA County Industrial Facilities to List of Nation's Worst Toxic Sites/Seam Master Industries and Jervis B. Webb Co. - both in South Gate", September 15, 2011.	2	No Redactions	None

Jervis Webb FOIA Review
CD Index
March 1, 2012

Doc #	Document Description	Total Pages	Folder	Pages Marked for Redaction
81	EPA Potential Hazardous Waste Site Preliminary Assessment Form, May 14, 1993.	4	No Redactions	None
82	Letter re: Scheduled Site Visit from Bechtel to Jervis B. Webb Co., May 2, 1994.	3	No Redactions	None
87	Transmittal of Final Site Assessment, Jervis B. Webb Co., South Gate, Los Angeles, CA., October 4, 1994.	6	No Redactions	None
89	Letter re: Proposed Listing of the Seam Master Industries and the Jervis B. Webb Co. Sites on the Superfund National Priorities List (NPL) from California Environmental Protection Agency to U.S. EPA Region IX, June 20, 2011.	2	No Redactions	None
90	Site Inspection Re-Assessment (SI-2) (prepared by CAL/EPA-Department of Toxic Substances Control; prepared for U.S. EPA Region IX), May 2002.	28	No Redactions	None
92	Letter re: Referral of Jervis B. Webb Company Site and Seam Master Site to the U.S. Environmental Protection Agency Region IX from Department of Toxic Substances Control to U.S. Environmental Protection Agency Region IX, January 18, 2011.	2	No Redactions	None
94	Transmittal List for Preliminary Assessment/Site Inspection, Site: Jervis B. Webb Co., January 19, 1995.	1	No Redactions	None
95	Case Summary, 979 F,2d 855: National Labor Relations board, Petitioner v. Jervis B. Webb Co., Respondent, (http://law.justia.com), accessed June 27, 2011.	6	No Redactions	None
96	"Jervis B. Webb Company Announces Completion of Acquisition to Daifuku Co., Ltd." (December 20, 2007), accessed July 1, 2011.	2	No Redactions	None
97	Contractor's License Detail - License No. 208901 for Jervis B. Webb Company of California, (www.2.cslb.ca.gov), accessed June 27, 2011.	2	No Redactions	None
98	State of California Board of Equalization Memorandum re: Construction Contractors, August 11, 1978.	5	No Redactions	None
99	YellowPages.com listing for Jervis B Webb Co in Farmington Hills, MI, (www.yellowpages.com), accessed July 11, 2011.	1	No Redactions	None
100	"CEO Susan Webb retires form Jervis B. Webb," (October 20, 2008), www.automation.com , accessed June 27, 2011.	1	No Redactions	None
101	WhitePages.com listing for Jervis B Webb Co in Farmington Hills, MI, (www.whitepages.com), accessed July 11, 2011.	2	No Redactions	None
102	Hoover's Company Profiles: Jervis B. Webb Company, (www.answers.com), accessed June 17, 2011.	6	No Redactions	None
103	United States Postal Service Zip Code Lookup, 34375 W. 12 Mile Road, Farmington Hills, MI, (http://zip4.usps.com), accessed July 11, 2011.	1	No Redactions	None
104	Decision and Order, Jervis B. Webb Company and United Brotherhood of Carpenters and Joiners of America, Local Union No. 1827, AFL-CIO, March 29, 1991.	6	No Redactions	None
105	Cortera Company Profile for Reliable Steel Building Products Inc., (http://start.cortera.com), accessed June 20, 2011.	1	No Redactions	None
106	Material Safety Data Sheet for Kill-Cide 700 manufactured by Rust-Lick, Incorporated.	2	No Redactions	None
107	Material Safety Data Sheet for Rustlick WS-11 manufactured by ITW ROCOL North America, December 15, 2008.	4	No Redactions	None
109	SWRCB Geotracker Profile, Jervis B Webb Co (SL2042J1538), (http://geotracker.swrcb.ca.gov), accessed June 17, 2011.	1	No Redactions	None
111	Envirofacts Facility Registry System, Facility Detail Report for Webb, Jervis B Co of California, 9301 So. Rayo, South Gate, CA 90280-3612 (http://iaspub.epa.gov/enviro/fii_query_dtl.disp_program_facility), accessed June 17, 2011.	4	No Redactions	None

Jervis Webb FOIA Review
CD Index
March 1, 2012

Doc #	Document Description	Total Pages	Folder	Pages Marked for Redaction
112	Department of Toxic Substances Control EnviroStor Profile, Jervis Webb (60000332), 9301 Rayo Ave., South Gate, CA 90280, (www.envirostor.dtsc.ca.gov), accessed June 17, 2011.	2	No Redactions	None
113	Envirofacts Facility Registry System, Facility Detail Report for Dial Corporation, 9300 Rayo Ave., South Gate, CA 90280 (http://iaspub.epa.gov/enviro/fii_query_dtl.disp_program_facility), accessed June 17, 2011.	8	No Redactions	None
114	Envirofacts Facility Registry System, Facility Detail Report for Piazza Trucking Inc., 9001 Rayo Ave., South Gate, CA 90280 (http://iaspub.epa.gov/enviro/fii_query_dtl.disp_program_facility), accessed June 17, 2011.	2	No Redactions	None
115	Groundwater Sampling Report - July 2003, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California (prepared by Brown and Caldwell; prepared for Regional Water Quality Control Board), July 30, 2003.	56	No Redactions	None
116	Quarterly Progress Report for January to March 1999 For the Jervis B. Webb Company Property at 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board Los Angeles Region), June 4, 1999.	31	No Redactions	None
117	Semi-Annual Groundwater Sampling Report - January 2003, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California (prepared by Brown and Caldwell; prepared for Regional Water Quality Control Board), January 28, 2003.	63	No Redactions	None
118	Document Summary	1	No Redactions	None
119	Work Plan for Clarifier Removal and Soil Remediation by Soil Vapor Extraction at the Jervis B. Webb Company Property Located at 5030 Firestone Boulevard, South Gate California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board Los Angeles Region), April 14, 1999.	20	No Redactions	None
120	Quarterly Progress Report for April through June 2001 For the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for Jervis B. Webb Company), July 24, 2001.	172	No Redactions	None
121	Letter re: 5030 Firestone Blvd and 9301 Rayo Ave, South Gate, CA, from Latham & Watkins to DTSC, January 30, 2002.	26	No Redactions	None
122	Quarterly Progress Report for January through March 2001 For the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for Jervis B. Webb Company), May 1, 2001.	91	No Redactions	None
123	Quarterly Progress Report for April through June 2000 For the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board), August 16, 2000.	101	No Redactions	None
124	Letter re: 5030 Firestone Blvd. and 9301 Rayo Ave., South Gate, CA, from Latham & Watkins to DTSC, January 29, 2002.	57	No Redactions	None
125	Groundwater and Soil Evaluation, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California (prepared by The Dracun Corporation and IT Corporation; prepared for Jervis B. Webb Company of California), May 22, 2001.	125	No Redactions	None
127	Letter re: Request to Modify Groundwater Sampling Methodology (and attached Semi Annual Groundwater Sampling Report, First Semester 2002, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, CA)(prepared by IT Corporation; submitted to California Regional Water Quality Control Board), February 28, 2002.	186	No Redactions	None

Jervis Webb FOIA Review
CD Index
March 1, 2012

Doc #	Document Description	Total Pages	Folder	Pages Marked for Redaction
128	Quarterly Progress Report for October to December 1999 For the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board), February 4, 2000.	40	No Redactions	None
129	Quarterly Progress Report for July through September 2000 For the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board), October 26, 2000.	196	No Redactions	None
130	Quarterly Progress Report for October through December 2000 and Request for No Further Action Regarding Soil for the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board Los Angeles Region), February 5, 2001.	165	No Redactions	None
131	Quarterly Progress Report for January through March 2000 For the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board), April 28, 2000.	111	No Redactions	None
132	Report on Site Conditions, Local Hydrogeology, and Offsite Groundwater Production and Work Plan for Groundwater Remediation for the Jervis B. Webb Company of California Property, 5030 Firestone Boulevard, South Gate, California (prepared by Erler & Kalinowski, Inc.; prepared for California Regional Water Quality Control Board), November 30, 2000.	78	No Redactions	None
133	Semi-Annual Groundwater Sampling Report - July 2002, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California (prepared by Brown and Caldwell; prepared for Regional Water Quality Control Board), July 30, 2002.	56	No Redactions	None
136	Letter re: Jervis Webb Site from Department of Toxic Substances Control to Reliable Steel Building Products, Inc., September 11, 2008.	11	No Redactions	None
138	Record of Communication re: Quarterly Monitoring Reports from Steven Hariri, California Regional Water Quality Control Board Los Angeles Region to Steven Chambers, California Regional Water Quality Control Board Los Angeles Region, July 11, 2000.	10	No Redactions	None
139	Power Point Presentation re: Jervis B. Webb Co. of California, July 11, 2001.	19	No Redactions	None
143	Letter re: Quarterly Groundwater Monitoring Report - Jervis B. Webb Company - 5030 Firestone Boulevard, South Gate, from RWQCB to Jervis B. Webb Company, September 18, 2000.	7	No Redactions	None
146	State of California Environmental Protection Agency California Hazardous Waste Permanent ID Number Application for Auburn Transmission, October 3, 2010.	1	No Redactions	None
148	Letter re: 104(e) Request for Information from Jervis B. Webb Company, October 4, 2011.	18	No Redactions	None
150	Letter re: 104(e) Request for Information from Reliable Steel Building Products, Inc., October 4, 2011.	13	No Redactions	None
151	Letter re: 104(e) Request for Information from 5030 East Firestone LLC, October 4, 2011.	13	No Redactions	None
153	Letter re: 104(e) Request for Information from United Motor Club Inc., October 4, 2011.	13	No Redactions	None
164	Letter re: Addendum to Work Plan for Soil Closure, Jervis B. Webb of California Site, 9030 Firestone Boulevard and 5030 Rayo Avenue, South Gate, CA, SLIC File No. 774, from IT Group to California Regional Water Quality Control Board, July 18, 2001.	8	No Redactions	None
170	Letter re: EPA placement of the Seam Master Industries and Jervis B. Webb Co. sites on the Superfund National Priorities List (NPL), from USEPA Region IX to the State of California, May 10, 2011.	2	No Redactions	None
171	HRS Documentation Record for Jervis B. Webb Co. (prepared by USEPA), September 2011.	1471	No Redactions	None

Jervis Webb FOIA Review
CD Index
March 1, 2012

Doc #	Document Description	Total Pages	Folder	Pages Marked for Redaction
30	Standard Offer, Agreement and Escrow Instructions for Purchase of Real Estate for Property Located at 5030 Firestone Blvd., South Gate, CA between Jose Ramirez (buyer) and Jervis B. Webb of California (seller)	10	Partial Redaction	p. 7 (home address & phone/fax numbers)
33	Letter re: Cleanup of Possible Contaminates at 9301 Rayo Ave., South Gate, CA (The Webb-Rayo Facility), from Jeffrey Palmer, President, Reliable Steel Building Products, Inc. to Department of Toxic Substances Control, February 29, 2008.	2	Partial Redaction	p. 2 (salary figure)
46	County of Los Angeles Department of Public Works Application for Closure of Hazardous Materials Underground Storage for Jervis B. Webb Company, October 28, 1996.	20	Partial Redaction	p. 15 (check numbers)
53	Work Plan for Soil Closure for 5030 Firestone Boulevard and 9301 Rayo Ave., South Gate, California (prepared by IT Corporation; prepared for Jervis B. Webb Company of California), June 25, 2001.	205	Partial Redaction	pp. 62-134 (VISTA Report - a subscription database)
72	Letter re: Cleanup of Possible Contaminates at 9301 Rayo Ave., South Gate, CA (The Webb-Rayo Facility), from Jeffrey Palmer, President, Reliable Steel Building Products, Inc. to Department of Toxic Substances Control, February 29, 2008.	2	Partial Redaction	p. 2 (salary figure)
73	104(e) Letter Response regarding Nikki L. Reagan (prepared by Nikki L. Reagan), November 14, 2011.	353	Partial Redaction	pp. 1, 2, 12 (home address and phone number; maiden name; AOL email address), pp. 16-21, 23-24, 26 (financing terms/\$ figures for property purchase), p. 27 (checking account info (PA) and \$ amt (potential CBI)), pp. 29-30, 32 (financing terms/\$ figures for property purchase), pp. 68-97 (VISTA Reports - paid subscription database), p. 257, 263 (scope of work costs, retainer \$ figure), pp. 277-348 (VISTA Reports - paid subscription database)
74	104(e) Letter Response regarding Mike Palm Club LLC (prepared by the Law Offices of Roger Jon Diamond), November 15, 2011.	6	Partial Redaction	p. 1 (home address and phone number)
75	104(e) Letter Response regarding United Motor Club, Inc. (prepared by Seyed M. Madaen), November 11, 2011.	2	Partial Redaction	p. 1 (annual gross revenue figures and asset figure)
76	104(e) Letter Response regarding 5030 East Firestone, LLC (prepared by Seyed M. Madaen), November 11, 2011.	2	Partial Redaction	p. 1 (annual gross revenue figure); p. 2 (home address on label)
86	U.S. EPA Triage Recommendation, Jervis Webb, 9301 Rayo Ave., South Gate, Los Angeles, CA 90280 - CAD 008339467, May 23, 2006.	14	Partial Redaction	pp. 1-5 (marked "Privileged and Confidential - Deliberative")
126	Consent Order for Jervis B. Webb of California Site, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California, October 23, 2008 (prepared by Department of Toxic Substances Control), October 23, 2008.	130	Partial Redaction	pp. 2, 3, 5, 54, 56, 59, 95, 97 (Privacy Act - home address); p. 53: (salary)
135	Transmittal of Consent Order for Jervis B. Webb of California Site, 5030 Firestone Boulevard and 9301 Rayo Avenue, South Gate, California, October 23, 2008 (prepared by Department of Toxic Substances Control), May 21, 2007.	37	Partial Redaction	pp. 1, 4 (Privacy Act - home address)
144	AMEC Files, Miscellaneous Correspondence involving RWQCB and other parties.	141	Partial Redaction	pp. 13-16 (case review form); p. 126 (email); p. 128 (cell phone number)
145	EPA Site Assessment Files, Folder #2, Miscellaneous Correspondence.	19	Partial Redaction	pp. 8, 12, 16 (home address); p. 19 (salary information)
147	Letter re: 104(e) Request for Information from Nikki L. Reagan, October 4, 2011.	11	Partial Redaction	pp. 1, 11 (home address)
149	Letter re: 104(e) Request for Information from Jeffrey M. Palmer, October 4, 2011.	11	Partial Redaction	pp. 1, 11 (home address)
152	Letter re: 104(e) Request for Information from Mike Palm Club, LLC, October 4, 2011, with Proof-of-Delivery from primary recipient, Mike Mudaris, Principal, Mike Palm Club, LLC.	13	Partial Redaction	pp. 1, 11 (possible home address)
165	Letter re: 104(e) Request for Information from Mike Palm Club, LLC, October 4, 2011, with Proof-of-Delivery from Carbon Copy recipient, David Seror, Trustee for the Mike Palm Club, LLC bankruptcy	13	Partial Redaction	p. 1 (possible home address)